



Facilities

Initial

Initial Facilities - Fire

Certificate of Service and Inspection No. 057263

Customer Name: KINGSTON VILLAGE HALL

Site Address:

BN7 3NT

Call Reference: ZG0176

This is to certify that Initial Facilities - Fire has undertaken the service, inspection and testing as listed below, except for any variations as stated on this certificate. The Regulatory Reform (Fire Safety) Order 2005 requires that the employer conducts a Fire Risk Assessment and that it should identify what fire detection, prevention and suppression equipment is necessary and that where it is deemed necessary the user should take reasonable steps to ensure its proper function.

- **Service of Portable Fire Extinguishers** in accordance with BS 5306-3
 - 6 Monthly
 - 12 Monthly
 - Other (enter Freq.)
- **Service of Hose Reels** in accordance with BS EN 671-3
 - 6 Monthly
 - 12 Monthly
 - Other (enter Freq.)
- **Service of Fire Alarm System** in accordance with BS 5839-1
 - Weekly
 - 3 Monthly
 - 6 Monthly
 - 12 Monthly
- **Service of Fixed Fire Suppression System** in accordance with BS EN 15004 - 1
 - Intermediate Service
 - Full Service
- **Inspection and testing of Emergency Lighting** in accordance with BS 5266-1
 - Weekly
 - 3 Monthly
 - 6 Monthly
 - 12 Monthly
- **Inspection and testing of Fire Hydrants** in accordance with BS5306: part 1
 - 6 Monthly
 - 12 Monthly
- **Inspection and testing of Dry Riser system** in accordance with BS9990
 - Visual Test 6 Monthly
 - Pressure Test 12 Monthly

● **Inspection of:**

enter frequency

Variations requiring corrective action refer to Work Sheet WS 057263

Engineer's Signature:

Engineer's Name: DUG MACKENZIE

Date of Service: 300714

Date of Next Service: 0715

Helpline: 0870 240 2545

518.V1.10.3069 LC:21.1761.22.77